

Water Testing Results - Canyonville

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Gym-Boys Locker Room	19940103-001BF	6/8/2022	1.7
Gym-Girls Locker Room	19940103-002BF	6/8/2022	ND
Community Center Kitchen Sink	19940104-001KF	6/8/2022	ND
Community Center Main Hall Fountain	19940104-002DW	6/8/2022	2.1
Annex Rm #1 Sink	19940101-001CF	6/8/2022	1.4
Annex Rm #1 Fountain	19940101-001DW	6/8/2022	4.4
Annex Rm #2 Sink	19940101-002CF	6/8/2022	1.3
Annex Rm #2 Fountain	19940101-002DW	6/8/2022	4.4
Annex Rm #3 Sink	19940101-003CF	6/8/2022	1.3
Annex Rm #3 Fountain	19940101-003DW	6/8/2022	ND
Annex Rm #4 Sink	1994010-004CF	6/8/2022	2.3
Main Bldg Rm #0-Computer Lab Sink	19940100-001CF	6/8/2022	11.6
Main Bldg Library Sink	19940100-009CF	6/8/2022	14
Main Bldg Rm #4 Sink	19940100-004CF	6/8/2022	11.8
Main Bldg Rm #5 Sink	19940100-005CF	6/8/2022	2.5
Main Bldg Rm #6 Sink	19940100-006CF	6/8/2022	7.9
Main Bldg North Hall Fountain	19940100-007DW	6/8/2022	23.2
Hilltop Lunch Rm Sink	19940101-006KF	6/8/2022	ND
Hilltop Rm #1 Sink	19940101-001CF	6/8/2022	2.2
Hilltop Rm #2 Sink	19940101-002CF	6/8/2022	ND
Hilltop Rm #4 Sink	19940101-004CF	6/8/2022	2
Hilltop Rm #3 Sink	19940101-003CF	6/8/2022	ND
Hilltop Staff Rm Sink	19940101-005SF	6/8/2022	ND

Any fixture testing at or above the action level of 15 ppb is IMMEDIATELY removed from service

RETESTS			
Main Bldg North Hall Fountain	19940100-007DW	10/17/2022	3.4

ND = Non Detect - Lead level is below the set detection limits of X ppb			