

Water Testing Results - Myrtle Creek Primary

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
1 Faucet	19940200-001CF	5/31/2022	0.0058
1 Sink	19940200-001DW	5/31/2022	0.0035
2 Sink	19940200-002CF	5/31/2022	0.0056
2 Fountain	19940200-002DW	5/31/2022	0.0039
3 Sink	19940200-003CF	5/31/2022	0.0025
3 Fountain	19940200-003DW	5/31/2022	0.0014
4 Sink	19940200-004CF	5/31/2022	0.0011
4 Fountain	19940200-004DW	5/31/2022	0.002
5 Sink	19940200-005CF	5/31/2022	0.0101
6 Sink	19940200-006CF	5/31/2022	0.007
6 Fountain	19940200-006DW	5/31/2022	0.0051
7 Sink	19940200-007CF	5/31/2022	0.0062
8 Sink	19940200-008CF	5/31/2022	0.0012
9 Sink	19940200-009CF	5/31/2022	0.0037
10 Sink	19940200-010CF	5/31/2022	0.0029
11 Sink	19940200-011CF	5/31/2022	0.0035
12 Sink	19940200-012CF	5/31/2022	0.0049
13 Sink	19940200-013CF	5/31/2022	0.0049
13 Fountain	19940200-0013CF/DW	5/31/2022 16:59	0.0044
14 Sink	19940200-0014CF/DW	6/7/2022 7:10	0.0053
14 Fountain	19940200-0014CF/DW	6/7/2022 7:10	0.0056
16 Sink	19940200-0016CF/DW	6/7/2022 7:15	0.0022
17 Sink	19940200-0017CF/DW	6/7/2022 7:18	0.0078
19 Sink	19940200-0018SF	6/7/2022 7:20	ND
20 Fountain	19940200-0019DW	6/7/2022 7:25	0.0037
21 Fountain	19940200-0020DW	6/7/2022 7:27	0.0029

Any fixture testing at or above the action level of 15 ppb is IMMEDIATELY removed from service

RETESTS			

ND = Non Detect - Lead level is below the set detection limits of X ppb