

# Water Testing Results - South Umpqua High School

## Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
HS Sr. Hall Chill Fountain	19940500-002BW	6/15/2022	ND
HS Kitchen Steamer Station	19940500-0300T	6/15/2022	5.2
HS Kitchen Baker Station	19940500-031KF	6/15/2022	6.1
HS Kitchen Cleaning Station	19940500-032KF	6/15/2022	5.2
HS Kitchen Prep S Station	19940500-033KF	6/15/2022	10.7
HS Blk MRK South Sink	19940500-012KF	6/15/2022	ND
HS Cons Std Lg Sink	19940500-0410T	6/15/2022	<b>22.1</b>
HS Cons Std Sm Sink	19940500-0420T	6/15/2022	4.1
HS DLC Left Sink	19940500-0410T	6/15/2022	1.1
HS DLC Mid Sink	19940500-004CF	6/15/2022	ND
HS DLC Right Sink	19940500-005CF	6/15/2022	4.6
HS DLC Hall Fountain	19940500-006CF	6/15/2022	ND
HS Freshman Hall Fountain	19940500-007DW	6/15/2022	ND
HS Office Hall Fountain	19940500-008DW	6/15/2022	7
HS Rm #22 Faucet	19940500-0221CF	6/15/2022	ND
HS Rm #22 South Faucet	19940500-0222CF	6/15/2022	ND
HS Student Store Ice Machine	19940500-011IM	6/15/2022	ND
HS Jr. Concession Faucet	19940500-0130T	6/15/2022	4.8
HS Locker Room Ice Machine	19940500-014IM	6/15/2022	6.8
HS Kitchen Ice Maker	19940500-034IM	6/15/2022	5.2
HS Band Room Faucet	19940500-009CF	6/15/2022	1
HS Office Break Room Faucet	19940500-010SF	6/15/2022	1.5
HS Concession Std Ice Maker	19940500-034IM	6/15/2022	<b>15.9</b>
HS V Baseball Field	19940500-051DW	6/15/2022	ND
HS Gym Fountain	19940500-017DW	6/15/2022	ND
HS Weight Room Fountain	19940500-0018DW	6/15/2022	ND
HS Dish Room Sink	19940500-0350T	6/15/2022	5.6

**Any fixture testing at or above the action level of 15 ppb is IMMEDIATELY removed from service**

HS Cons Std Lg Sink	19940500-041OT	10/12/2022	1.8
HS Concession Std Ice Maker	19940500-034IM	10/12/2022	2.1

ND = Non Detect - Lead level is below the set detection lir of X ppb