

Water Testing Results - Tri City Elementary

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Rm #1 Fountain	19940400-001CF	6/9/2022	2.6
Rm #2 Fountain	19940400-002CF	6/9/2022	1.3
Rm #5 Fountain	19940400-005CF	6/9/2022	67.9
Rm #7 Fountain	19940400-007CF	6/9/2022	4.5
Rm #10 Fountain	19940400-0010CF	6/9/2022	6.7
Rm #12 Fountain	19940400-0012CF	6/9/2022	7.3
Rm #14 Fountain	19940400-0014CF	6/9/2022	5.3
Rm #15 Fountain	19940400-00 15CF	6/9/2022	3
Rm #16 Fountain	19940400-0016CF	6/9/2022	5.5
Rm #17 Fountain	19940400-0017CF	6/9/2022	2.7
Rm #18 Fountain	19940400-0018CF	6/9/2022	14.5
Kitchen N Faucet	19940400-0019KF	6/9/2022	115
Kitchen W Faucet	19940400-0020KF	6/9/2022	2.5
Rm #28 Fountain	19940401-028DW	6/9/2022	2.1
Rm #29 Fountain	19940401-029DW	6/9/2022	3
Rm #30 Fountain	19940401-030DW	6/9/2022	ND

Any fixture testing at or above the action level of 15 ppb is IMMEDIATELY removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			
Rm #5 Fountain	19940400-005CF	10/17/2022	11.3
Kitchen N Faucet	19940400-0019KF	10/17/2022	ND

ND = Non Detect - Lead level is below the set detection limits of X ppb