

Water Testing Results - Skyhawk

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
West Dish Sink	19940202-001KF	6/8/2022	ND
South East Sink	19940202-002KF	6/8/2022	3.3
North East Sink	19940202-003KF	6/8/2022	1.3
Multi Purpose Room Fountian	19940202-004DW	6/8/2022	ND
Annex South Room Sink	19940203-001CF	6/8/2022	ND
Annex South Room Fountain	19940203-001DW	6/8/2022	ND
Annex North Room Sink	19940203-002CF	6/8/2022	ND

Any fixture testing at or above the action level of 15 ppb is IMMEDIATELY removed from service and cannot be returned to service until it has been remediated and passed follow-up testing

RETESTS			

ND = Non Detect - Lead level is below the set detection limits of X ppb