
November 14, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
SOUTH UMPQUA H.S.

| Kit # | Room Id | Started | Ended | pCi/L | Analyzed |
|--------------|----------------|----------------------|----------------------|--------------|-----------------|
| 8734077 | | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
SOUTH UMPQUA H.S.
MAIN

| Kit # | Room Id | Started | Ended | pCi/L | Analyzed |
|---------|------------------|----------------------|----------------------|-------|------------|
| 8734032 | 1 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734030 | 10 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734055 | 11 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734054 | 12 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734037 | 13 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734066 | 14 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734060 | 16 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734063 | 17 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734003 | 18 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734002 | 19 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734039 | 2 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734031 | 20 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734052 | 21 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734064 | 23 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734019 | 27 | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734078 | 28 | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734057 | 3 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734018 | 30 | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734061 | 4 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734070 | 6 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734068 | 7 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734036 | 8 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734040 | 9 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734084 | A-1 | 2018-10-29 @ 8:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734085 | A-2 | 2018-10-29 @ 8:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734083 | A-3 | 2018-10-29 @ 8:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734017 | ART ROOM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734059 | BAND OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734062 | BAND RM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734065 | BAND ROOM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734045 | COLLEGE OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734049 | COPY RM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734001 | CUSTODIAL OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734004 | DEPT OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734043 | DLC | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734056 | DLC | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734042 | DLC OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |

Radon test result report for:
SOUTH UMPQUA H.S.
MAIN

| Kit # | Room Id | Started | Ended | pCi/L | Analyzed |
|---------|------------------|----------------------|----------------------|------------|------------|
| 8734058 | DRAMA | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734048 | DRAMA OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | 18.5 ± 0.7 | 2018-11-03 |
| 8734044 | FACULTY RM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734009 | GYM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734072 | GYM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734016 | GYM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734076 | GYM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734020 | GYM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | 17.0 ± 0.6 | 2018-11-03 |
| 8734008 | GYM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734024 | GYM LOBBY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734025 | GYM LOBBY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734082 | ISS ROOM | 2018-10-29 @ 8:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734081 | KITCHEN OFFICE | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734029 | LIBRARY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734050 | LIBRARY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734028 | LIBRARY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734051 | LIBRARY OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734021 | METAL OFFICE | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734012 | METAL SHOP | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734013 | METAL SHOP | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734069 | MULTI PURPOSE RM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734079 | MULTI PURPOSE RM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734010 | MULTI PURPOSE RM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734011 | MULTI PURPOSE RM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734073 | O1 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734034 | O2 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734033 | O3 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734027 | O4 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734074 | O5 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734026 | O6 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734075 | O7 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734071 | O8 | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734041 | OFFICE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734053 | OFFICE LOBBY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734035 | OFFICE WORK | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734067 | SICENCE LAB | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734006 | STAGE | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |

November 14, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
SOUTH UMPQUA H.S.
MAIN

| Kit # | Room Id | Started | Ended | pCi/L | Analyzed |
|--------------|----------------|----------------------|----------------------|--------------|-----------------|
| 8734080 | STAGE | 2018-10-29 @ 7:00 am | 2018-11-01 @ 7:00 am | < 0.3 | 2018-11-03 |
| 8734046 | STUDY | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734014 | WEIGHT RM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | 0.6 ± 0.2 | 2018-11-03 |
| 8734015 | WEIGHT RM | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734007 | WOODSHOP | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734022 | WOODSHOP OFF | 2018-10-29 @ 7:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |
| 8734047 | WORK RM | 2018-10-29 @ 6:00 am | 2018-11-01 @ 6:00 am | < 0.3 | 2018-11-03 |

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:
SOUTH UMPQUA S.D.
DIST OFFICE

| Kit # | Room Id | Started | Ended | pCi/L | Analyzed |
|--------------|----------------|----------------------|----------------------|--------------|-----------------|
| 8734091 | 14 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734092 | 18 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | 0.7 ± 0.2 | 2018-11-03 |
| 8734093 | 18 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734094 | 19 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734095 | 22 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | 5.1 ± 0.3 | 2018-11-03 |
| 8734090 | 22 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734097 | 23 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734100 | 24 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | 5.2 ± 0.4 | 2018-11-03 |
| 8734088 | 5 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734099 | 6 | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |
| 8734098 | BOARD ROOM | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | 5.3 ± 0.4 | 2018-11-03 |
| 8734096 | BOARD ROOM | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | 4.3 ± 0.3 | 2018-11-03 |
| 8734089 | BREAK ROOM | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | 0.5 ± 0.2 | 2018-11-03 |
| 8734086 | LOBBY | 2018-10-29 @ 9:00 am | 2018-11-01 @ 8:00 am | < 0.3 | 2018-11-03 |