

Water Testing Results - Canyonville

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Gym-Boy's Locker Room		7/20/2016	5
Gym-Girls' Locker Room		7/20/2016	2
Community Center Kitchen Sink		7/27/2016	ND
Community Center Main Hall Fountain		7/27/2016	ND
Annex Rm #1 Sink/Fountain		7/20/2016	34
Annex Rm #2 Sink/Fountain		7/20/2016	2
Annex Rm #3 Sink/Fountain		7/20/2016	15
Annex Rm #4 Sink/Fountain		7/20/2016	14
Main Bldg Rm #0-Computer Lab Sink		7/20/2016	10
Main Bldg Library Sink		7/20/2016	15
Main Bldg Rm #4 Sink		7/20/2016	10
Main Bldg Rm #5 Sink		7/20/2016	4
Main Bldg Rm #6 Sink/Fountain		7/20/2016	7
Main Bldg Rm #6 Sink		7/20/2016	5
Main Bldg North Hall Fountain		7/20/2016	7
Main Bldg South Hall Fountain		7/20/2016	13
Hilltop Lunch Rm Sink		7/20/2016	ND
Hilltop Rm #1 Sink		7/20/2016	4
Hilltop Rm #2 Sink/Fountain		7/20/2016	28
Hilltop Rm #4 Sink		7/20/2016	4
Hilltop Rm #5 Sink		7/20/2016	14
Hilltop Staff Rm Sink		7/20/2016	21