

**Water Testing Results - Myrtle Creek Primary Bldg**  
**Action Level is 15 parts per billion (ppb)**

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Rm#1 Sink/Fountain		8/5/2016	4
Rm #2 Sink/Fountain		8/5/2016	5
Rm #3 Sink/Fountain		8/5/2016	8
Rm #4 Sink/Fountain		8/5/2016	3
Rm #5 Sink/Fountain		8/5/2016	5
Rm #6 Sink/Fountain		8/5/2016	10
Rm #7 Sink/Fountain		8/5/2016	9
Rm #8 Sink/Fountain		8/5/2016	4
Rm #9 Sink/Fountain		8/5/2016	4
Rm #12 Sink		8/5/2016	5
Rm #13 Sink		8/5/2016	8
Rm #15 Sink		8/5/2016	5
Rm #16 Sink/Fountain		8/5/2016	6
Rm #17 Sink/Fountain		8/5/2016	8
Library Sink		8/5/2016	8
Computer Lab Sink		8/5/2016	8
Office Sink		8/5/2016	6
Outside Fountain		8/5/2016	8
Staff Work Rm Sink		8/5/2016	2
Hallway Fountain by Rm #6		8/5/2016	4
Hallway Fountain by Rm #12		8/5/2016	3

**Water Testing Results - Myrtle Creek Intermediate Bldg**  
**Action Level is 15 parts per billion (ppb)**

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Rm #18 Faucet		8/3/2016	ND
Rm #19 Faucet		8/3/2016	6
Rm #20 Faucet		8/4/2016	2
Rm #21 Faucet		8/4/2016	4
Rm #22 Faucet		8/4/2016	3
Rm #23 Faucet		8/4/2016	2
Rm #24 Faucet		8/4/2016	4
Rm #25 Faucet		8/4/2016	ND
Rm #27 Faucet		8/3/2016	ND
Hallway Drinking Fountain		8/3/2016	ND

**Water Testing Results - Skyhawk & MC Annex**  
**Action Level is 15 parts per billion (ppb)**

Fixture Location/Description	Fixture ID #	Test Date	Test Result
West Dish Sink		8/8/2016	5
South East Sink		8/8/2016	5
North East Sink		8/8/2016	7
Multi Purpose Room Fountain		8/8/2016	ND
Annex South Room Sink/Fountain		8/8/2016	ND
Annex North Room Sink/Fountain		8/8/2016	ND